



Wire Harness Processing Specialists
877-7AERO-US

GM ECM Backshells

Why replace the whole connector? GM mounts an Engine Control Module (ECM) in a vulnerable location behind the radiator. If a frontal impact is severe enough the radiator and its support collapses onto the ECM and cracks or crushes the protective cover on the ECM connector.

In the past, it was necessary to replace the connector or harness assembly for these broken back shells. Not anymore! **Aeromotive** now provides the back shell only. *Talk about savings!* Here, take a look.

\$39.80/ea



\$39.80/ea

Have a Safe
4th of July!



www.aeromotive.us

877-7AERO-US

(877-723-7687)

